

# Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER Meridian CUSD 223	COUNTY Ogle
FACILITY NAME Monroe Center Grade School	FACILITY LOCATION 17500 Hwy 72 ,PO Box 360, Monroe Center

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 10/24/2024 by Josh Knuth.

**Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.**

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
3	Administration and General	Annual review of crisis plan needed
6	Administration and General	Emergency/exit light by room 2
12	Administration and General	System is in trouble
13	Administration and General	Repair deficiencies noted on the annual sprinkler system report
14	Administration and General	Clearance to ceiling needed in room 8, PE office, old kitchen
22	Administration and General	Fire rating of couch in room 15 needed
23	Administration and General	Ceiling tile in janitorial closet by library, storage room by small gym, and room 23
25	Administration and General	Provide GFI for drinking fountains
94	Classrooms	Closers needed throughout non-sprinkled area; doors need to latch throughout sprinkled area
97	Classrooms	Remove artwork over door in room 23
112	Corridors	Door I not latching
143	Gym and Mulitpurpose Rooms	Door not latching in big gym
283	Storage/Supply/Closets	Double doors to storage off kitchen not latching in
301	Teachers Workrooms and Lounges	Door J needs closure
700	Other Items	Housekeeping needed in old kitchen