

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER Pana Community Unit School District No. 8	COUNTY Christian/Montgomery
FACILITY NAME Senior High School	FACILITY LOCATION 201 West 8th Street, Pana

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 01/10/2023 by Dean Keller.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
1	Administration and General	All rooms should post emergency egress plans.
14	Administration and General	Replace tiles in NE stairwell
25	Administration and General	Confirm outlet by kitchen dishwasher is gfi, rm 134 needs some plate covers, confirm raceway outlets in science are gfi. Cover in coaches office broken.
74	Boiler Room	Applied for
122	Elevator and Conveying Systems	Applied for
152	Home Economics and Family Service	Need CO detector.