

STATEMENT OF COMPLETION FOR HEALTH/LIFE SAFETY AMENDMENT

(Required By 23 IL Administrative Code Part 180)

The Board of Education for Pana CUSD #8, in
District Name and Number

Christian County, upon resolution adopted at a duly convened meeting, hereby proclaims the

work outlined in the Health and Safety Survey/Amendment # 1 report for the New Pana Sr High
School building at 201 W 8th Street, Pana, Illinois, as required under Section 2-3.12 of,
Address of School

the School Code of Illinois, approved by the State Superintendent on 5/19/2011 in the Amount of \$

0.00 and with an Actual Expense of \$ 0.00, has now been completed.


WHEREAS, The Safety Survey Report/Amendment described certain conditions of the building that did not comply with health and safety requirements as set out in **Building Specifications for Health and Safety in Public Schools**, 23 IL ADM Code 185, **Efficient and Adequate Standards for the Construction of Schools**, 23 IL ADM Code 175, and/or **Health/Life Safety for Public Schools**, 23 IL ADM Code Part 180;

WHEREAS, The Board of Education of School District No. 8, in Christian County, has caused to be effectuated such recommendations contained within the Safety Survey Report as necessary to cause compliance with Part 185, 175 and/or 180;

NOW, therefore, we _____, President of the Board of Education of School District

No. 8 in Christian County, Illinois and John S. Whitlock, the responsible architect or engineer, state that

the above named Safety Survey Report or Amendment is now in compliance with Part 185, 175 and/or 180.



Date *Signature of President of the School Board*

Date *Signature of District Superintendent*

2.6.18
Date

Signature of Architect/Engineer

The report of District # 8 has been reviewed. The statements of the Architect and/or Engineer and District Officials provide assurance that all requirements of 23 IL ADM Code, Parts 175, 185 & 180, have been

met, regarding work at the New Pana Sr High School.
(Building Name)

Date

Signature of Regional Superintendent

County

APPLICATION FOR OCCUPANCY

DISTRICT NAME AND NUMBER Pana CUSD #80	<input checked="" type="checkbox"/> GENERAL CERTIFICATE OF OCCUPANCY <input type="checkbox"/> CERTIFICATE OF PARTIAL OCCUPANCY <input type="checkbox"/> CERTIFICATE FOR A VEHICULAR FACILITY <input type="checkbox"/> CERTIFICATE OF TEMPORARY OCCUPANCY
FACILITY NAME New Pana Sr High School	
FACILITY LOCATION 201 W 8 th Street, Pana Illinois	
<input checked="" type="checkbox"/> Property is owned by the district. <input type="checkbox"/> Property is not owned by district (Attach Owner Authorization)	<input type="checkbox"/> New Use - Bldg Permit # _____ <input type="checkbox"/> New Construction - Project # _____ Bldg Permit # _____ <input type="checkbox"/> Addition - Project # _____ Bldg Permit # _____ <input type="checkbox"/> Renovation/Repair - Project # _____ Bldg Permit # _____


III. ARCHITECT/ENGINEER'S CERTIFICATION

To the best of my knowledge and belief (check and complete applicable statement):

- ☒ 1. Based upon my survey of the above named facility on 06 / 30 / 2010 I find and hereby certify that the facility is in full compliance with Part 180. The INSPECTION STATEMENTS and the CONFIRMATION OF CALLED INSPECTION RECORDS have been submitted to, and the CALLED INSPECTIONS RECORDS have been reviewed by the Regional Superintendent during and/or upon completion as applicable to the work.
- ☐ 2. I find that the facility fails to comply fully with the requirements of Part 180. However, based upon my survey of the above named facility on ___/___/___ and the attached TEMPORARY FACILITY REPORT (includes the Temporary Facility Elimination Plan and the Temporary Facility Checklist), I hereby certify that such noncompliance does not jeopardize the general health and safety of the student and others who occupy the facility.
- ☐ 3. Based upon my survey of the work within the above named facility on ___/___/___ I find and hereby certify that the work is in full compliance with Part 180. The INSPECTION STATEMENTS and the CONFIRMATION OF CALLED INSPECTION RECORDS have been submitted to, and the CALLED INSPECTIONS RECORDS have been reviewed by the Regional Superintendent during and/or upon completion as applicable to the work.

This statement, as selected above, is valid as of the day of the survey indicated. Changes to the facility or conditions affecting it after that date may render this statement invalid.

Date	John S. Whitlock Architect/Engineer Name	BLDD Architects, Inc. Firm Name
	001-017760 License Number	844-784-4440 Phone Number



SCHOOL DISTRICT CERTIFICATION

We hereby certify that this application accurately describes the status of the work and the occupancy we are seeking in order to occupy the above named facility for the primary purpose of: _____

Date _____	President of the Board of Education _____
Date _____	District Superintendent _____

FOR REGIONAL SUPERINTENDENT'S USE

INSPECTION RECORDS: Date Reviewed: ___/___/___

INSPECTION STATEMENT: Date Received: ___/___/___

CONFIRMATION OF CALLED INSPECTION RECORDS: Date Received: ___/___/___

An inspection was made or caused to be made upon the completion of the work and before issuance of a CERTIFICATE OF OCCUPANCY for the above named facility on ___/___/___ Any violations of the approved construction documents and building permits were noted, and the holder of the permit was notified of the discrepancies. No certificate of occupancy was issued until the discrepancies were remedied.

Date _____ Regional Superintendent _____

STATEMENT OF COMPLETION FOR HEALTH/LIFE SAFETY AMENDMENT


(Required By 23 IL Administrative Code Part 180)

The Board of Education for Pana CUSD 8, 0080, in Christian County, upon resolution adopted at a duly convened meeting, hereby proclaims the work outlined in the Health and Safety Survey/Amendment #1 report for the New Pana Sr High School building at 201 W. 8th St., Pana, Illinois, as required under section 2-3.12 of, the School Code of Illinois, approved by the State Superintendent on 5/19/2011 in the amount of \$0.00 and with an actual expense of \$0.00....., has now been completed.

WHEREAS, the Safety Survey Report/Amendment described certain conditions of the building that did not comply with health and safety requirements as set out in **Building Specifications for Health and Safety in Public Schools**, 23 IL ADM code 185, **Efficient and Adequate Standards for the Construction of Schools**, 23 IL ADM Code 175, and/or **Health/Life Safety for Public Schools**, 23 IL ADM Code Part 180;

WHEREAS, The Board of Education of School District No 0080, in Christian County, has caused to be effectuated such recommendations contained within the Safety Survey Report as necessary to cause compliance with Part 185, 175 and/or 180;

NOW, therefore, we , Mr. Donald Allen, President of the Board of Education of School District No. 0080 in Christian County, Illinois and Samuel J. Johnson, the responsible architect or engineer, state that the above named Safety Survey Report or Amendment is now in compliance with Part 185, 175 and/or 180;

Date	Signature of President of the School Board
Date	Signature of District Superintendent
2/1/2018	
Date	Signature of Architect/Engineer

The report of District #0080 has been reviewed. The statements of the Architect and/or Engineer and District Officials provide assurance that all requirements of 23 IL ADM Code, Part 175, 185 & 180, have been met, regarding work at the New Pana Sr High School.

Date

Signature of Regional Superintendent

Christian

County

NOTE: Needs "NA," and **Signature** in each section if does not apply. No seal required.

CONFIRMATION OF CALLED INSPECTION RECORDS

School Building/Facility Name: New Pana Sr High School

Amendment/Project: #1 / Band – Chorus Horn/Strobe Replacement

☐ **2015 International Building Code Called Inspection Records**

	Called Inspection Type	Approval to Proceed Date	A/E or Qualified Inspector Signature	ISBE ID Number or A/E License Number
1.	Footing	N/A		
2.	Foundation	N/A		
3.	Concrete Slab / Under-floor	N/A		
4.	Lowest Floor Elevation	N/A		
5.	Framing	N/A		
6.	Lathe and Gypsum Board	N/A		
7.	Fire Resistant Penetrations	N/A		
8.	Energy Efficiency	N/A		
9.	Special Inspection	N/A		
10.	Final IBC	N/A		

☐ **2015 International Electrical Code (Appendix K) Called Inspection Records**

	Called Inspection Type	Approval to Proceed Date	A/E or Qualified Inspector Signature	ISBE ID Number or A/E License Number
1.	Prefabricated Assembly Evaluation Report	N/A		
2.	Underground	N/A		
3.	Rough-in	N/A		
4.	Final IEC	N/A		

☐ **2015 International Energy Conservation Code Called Inspection Records**

	Called Inspection Type	Approval to Proceed Date	A/E or Qualified Inspector Signature	ISBE ID Number or A/E License Number
1.	Foundation (thermal envelope)	N/A		
2.	Framing (thermal envelope)	N/A		
3.	Insulation (thermal envelope)	N/A		
4.	Rough-in "Okay to Cover" (mechanical, service water heating, electrical, lighting)	N/A		
5.	Final (mechanical, service water heating, electrical, lighting)	N/A		
6.	Final IECC	N/A		

v

☐ **2015 International Fire Code Called Inspection Records**

	Called Inspection Type	Approval to Proceed Date	A/E or Qualified Inspector Signature	ISBE ID Number or A/E License Number
1.	Final IFC	N/A		

☐ **2015 International Mechanical and Fuel Gas Code Called Inspection Records**

	Called Inspection Type	Approval to Proceed Date	A/E or Qualified Inspector Signature	ISBE ID Number or A/E License Number
1.	Prefabricated Assembly Evaluation Report	N/A		
2.	Underground Piping	N/A		
3.	Rough-in	N/A		
4.	Final IMC & IFGC	N/A		