

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER Meridian CUSD 223	COUNTY Ogle
FACILITY NAME Meridian Jr High School	FACILITY LOCATION 207 W Main St, Stillman Valley

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 10/24/2024 by Josh Knuth.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
4	Administration and General	Hold-opens on gym doors and boys' locker room
5	Administration and General	Gym mezzanine egress has a hasp-style lock which needs to be removed
6	Administration and General	Emergency/exit light outside room 101, southwest 2nd floor and boys' locker room
12	Administration and General	Repair deficiencies noted on the annual alarm system report
14	Administration and General	Clearance to ceiling needed in main office storage closets and room 124
15	Administration and General	Repair deficiencies noted on the annual sprinkler system report
22	Administration and General	Fire rating needed on chairs in room 127
23	Administration and General	Open ceiling hatch main office closets; ceiling tile room 218 and band room storage
24	Administration and General	Multi plug adapter in room 201; extension cord room 210
25	Administration and General	Excessive lights hanging from lights in room 201
85	Cafeteria (A)	Doors not closing and latching; hinge broken
111	Corridors	Emergency light at top of stairs west
112	Corridors	Doors east 2nd floor not latching in
114	Corridors	Remove tables in corridor by rooms 201/202
138	Gym and Multipurpose Rooms	Occupant load sign needed in balcony weight room
143	Gym and Multipurpose Rooms	Gym doors to south corridor not latching in
241	Solar Photovoltaic Power Systems, Roof Mounted	Mark the shutoff
266	Stages with Storage Underneath	Remove combustibles
283	Storage/Supply/Closets	Door needs to latch on janitorial closet by room 212
700	Other Items	Housekeeping needed in IT room off library