

Harvey School District #152

District – Wide Major Repair & Maintenance Report

APRIL / MAY 2013

1. Set-up Tables at Riley, Angelou, Lowell, Whittier, & Sandburg for Election Day
2. Ordered New Hot Water Steam Boiler for Kitchen at Brooks Middle School
3. Installed New Pads and Batteries for AED'S Equipment District-Wide
4. Repaired Electrical outlet on wall in computer lab at Sandburg School
5. Installed New Water Faucets & Toilets & Urinals Parts District-Wide
6. Painted boys and girls bathroom walls South & West areas & Repaired Floor Drain in North Hallway & Install New Light Covers in Lecture Hall & Ceiling Tiles at Brooks Middle School
7. Repaired Cracks in walls & Painted walls in Class rooms 126 & 206 at Maya Angelou School
8. Repaired & (Sealed Cracks in Walls with Concrete & Painted Areas affected) in hallway area at Administration/Riley Bldg.
9. Repaired basketball backboards and rims in the gym at Lowell & Angelou
10. Repaired Main Front Outside Doors at Angelou School
11. Repaired A/C units for Offices 129, 132, & 134a at Administration/Riley Center
12. Repaired faucet and replaced damaged floor tile at Riley Pre-K School
13. Repaired Leaking Heating Unit on Stage for gym area at Riley Pre-K School
14. Replaced broken toilet in the girls washroom & boys washrooms & Installed New sink faucets at Bryant School
15. Repaired sinks and toilets & Adjust Water Flow in all boys bath room Urinals & Repair Auto-Sensors at Maya Angelou School
16. Repaired Sink Leak in Girls and Boys bathrooms & Installed New Sink Faucet in Office bathroom for usage & Repaired Front Door Main Entry at Holmes School
17. Repaired Girls Washroom Toilet Leaks on Old side & Toilet Leaks on New side at Holmes school
18. Repaired Roof Top A/C Unit Leak & Repaired Office Entry Door at Brooks Middle School
19. Monthly Bldg. Inspections District Wide
20. Repaired Toilets & Urinals and Office Uni-Vent Leak at C.L.A.S.S. Bldgs./ Fields
21. Repaired Hot Water Tank Leak in Boiler room at Fields/C.L.A.S.S. Bldgs
22. Repaired Boiler Pump Leaks for Bldg. Heat in Boiler Room at Whittier School
23. Installed (3) Class Rooms Wall Control Units for heat at Brooks Middle School
24. Action Fire Equipment Annual Service on Portable Fire Extinguishers District-Wide
25. ITR Systems Fire Alarm Inspections District-Wide
26. Installed Camera Racks for Servers at Holmes, Lowell, Whittier, Sandburg, Brooks
27. District Wide Cleaning of Grease Traps
28. Order & Repair (2) Windows, Main Front Entry Door & Secretary Office at Sandburg School
29. Completed (28) work orders District-Wide

Note: Minor daily operation type repairs are not listed on this report.