## **QUOTE TABULATION**

## GLASS REPLACEMENT SERVICES

## for the period of July 1, 2018 through June 30, 2019 QUOTE #4287

Thursday, February 15, 2018 - 2:15 p.m.

		OURLY RAT		THICKNESS (price per square foot)					Estimated		
Vendor	Regular	Overtime	Holiday	Type of Glass	1/8"	3/16"	1/4"	3/8"	1/2"	Mullion	Total
Arrowhead Window & Door 606 Elk Street Duluth, Minnesota 55803 phone: 218-729-9000				clear plate							The state of the s
				clear tempered							
				DSB window							
				clear insulated							
				obscured insulated							
	VINEZARIZMONI PRINCIPARENTE CONTRA CARROLLA CARROL		\$25 William   10 Percent   10 P	low "E" insulated							
Duluth Glass & Mirror Co. 4609 Grand Avenue Duluth, Minnesota 55807 phone: 218-727-8596				clear plate							
				clear tempered							
				DSB window							
				clear insulated							
				obscured insulated							
				low "E" insulated							
St. Germain's Glass Co 212 North 40th Avenue West Duluth, Minnesota 55807 phone: 218-628-0221				clear plate	A CONTRACTOR OF THE PARTY OF TH		William Charles and Charles an	A Section of the sect	CONTRACTOR OF THE PARTY OF THE		eritti eta 1900a eta 1901koko erroltario 1811 kunisten eta 1911
				clear tempered							
				DSB window							
				clear insulated							
				obscured insulated							
				low "E" insulated							
<b>Superior Glass, Inc.</b> 823 Belknap Street Superior, Wisconsin 54880 phone: 715-394-5588	\$77.08	8 \$115.62	\$154.16	clear plate	\$3.99	\$5.05	\$5.65	\$9.98	\$16.93	\$4.34	\$23,124.00
				clear tempered	\$8.03	\$8.62	\$8.67	\$13.10	\$18.74		
				DSB window	\$3.99						
				clear insulated	\$10.68	\$10.73	\$10.79				
				obscured insulated	\$18.40	\$18.56	\$18.56				
				low "E" insulated	\$14.07	\$14.12	\$14.23				
The Glass Guru of Duluth 102 East Central Entrance Duluth, Minnesota 55811 phone: 218-624-2119		Control of the Contro		clear plate	nassovialis maksi kirassisansi	AND SERVICE SKEWS STATE OF STA	Marine na haar kan ara ar kan kan kan kan ka	en e			
				clear tempered			***************************************				
				DSB window							
				clear insulated	VIII.						
	-			obscured insulated							
				low "E" insulated	***************************************						