School Site: Central Office
Date Inspected January 24, 2011

Inspected By Julie Hinds

Main Entrance	U	N	S	E	Classrooms	U	N	S	E
Appearance					Dust/Cobwebs			V	
Dust/Cobwebs					Doors and Facing			\mathbf{V}	
ing transparies for the members of the second of the secon					Floors and Waste Basket			\mathbf{Z}	
Restrooms	U	N	S	E	Restrooms (cont'd)	U	N	S	: E
Floors Cleaned and Disinfected			[Z]		Doors cleaned			V	
Ceiling and walls free from debris			(Y)		Mirrors cleaned			Ø	
Soap, toilet paper and paper towels re-supplied			Ø		Graffiti removed				
Trash containers emptied and cleaned	a		*******	NORMAN .	Chrome or stainless steel polished				
Sinks cleaned			$[\mathbf{V}]$		Walls and partitions cleaned				
Toilets cleaned					All surface areas dusted				
Urinals cleaned		(esés)			ത്ത്യ അവര് 2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			*	
austronium automium kontrante estimauri nito teasiferen il petio fest, sermos to estiment evat ele en a i mal Gym	U	N	S	E	Cafeteria/Kitchen	U	N	S	E
Floors					Tables				
Doors, Facings & Windows					Floors				
Appearance					Trash Containers				
Dust/Cobwebs					Doors, Facings & Windows				
	n-A Draw				Appearance		[14]		
ig general a como casa esta que o que procurada en car qualque emercamine medificamente que um absencio en cas				je zaze	Dust/Cobwebs				
Grounds	U	N	s	E	General	U	N	S	Ε
Appearance					Graffiti				
Flower Beds					Drinking Fountains				
Litter			Ø		Mechanical/Electrical Rooms Orderly			(Z)	
Supplies	U	N	S	E	Custodial Equipment	U	N	S	E
Cleanliness, organization & supply of custodial room			Z		Stored Correctly			(V)	
Control of Supplies			[]		Properly Cleaned			V	
			American construction	Section of the sectio	In Good Repair(Mechanical & Electrical)			(Z)	
	- 				Overall School Site Condition:			V	i (a)

School Site:

Central Supply

Date Inspected: 1-6-11

Inspected By: Trent Pannell

U Unsatisfactory N Needs Improvement S Satisfactory E Exceeds Standards

Main Entrance	U	N	S	E	Classrooms	U	N	s i	E
Appearance	الفقا		V		Dust/Cobwebs	لقظ	(a)		\mathbf{V}
Dust/Cobwebs	اقتا	\mathbb{Z}	وغيونا	(NEID)	Doors and Facing	(E)	14 (2)		
discuss the second seco		وقعد		(Floors and Waste Basket	☑	الس		
Restrooms	U	N	s	E	Restrooms (cont'd)	U	N	s	E
Floors Cleaned and Disinfected	$ \mathbf{Z} $	(wis)			Doors cleaned		(دين	(V)	
Ceiling and walls free from debris		(<u>63</u>)	Ø		Mirrors cleaned	العقا		V	
Soap, toilet paper and paper towels re-supplied		Ø			Graffiti removed			Ø	
Trash containers emptied and cleaned			Z	وفقين	Chrome or stainless steel polished	(SE	(<u>17.65</u>)	V	
Sinks cleaned		V			Walls and partitions cleaned			V	
Toilets cleaned		ريق ا	\mathbf{Z}		All surface areas dusted			$[\mathbf{V}]$	
Urinals cleaned			Ø	(E)					
Gym	υ	N	s	E	Cafeteria/Kitchen	U	N	s	Е
Floors					Tables				
Doors, Facings & Windows				(East)	Floors	(Laggi			
Appearance					Trash Containers				
Dust/Cobwebs					Doors, Facings & Windows				(<u>E. 16</u>)
		1			Appearance				
A STATE OF THE STA	.,,				Dust/Cobwebs				
Grounds	U	N	S	E	General	U	N	s	E
Appearance					Graffiti				
Flower Beds	الفقاً		(11)		Drinking Fountains				
Litter	1				Mechanical/Electrical Rooms Orderly				(Eus)
Supplies	U	N	S	E	Custodial Equipment	U	N	s	E
Cleanliness, organization & supply of custodial room			Z		Stored Correctly	tig	(22)	الاستا	V
Control of Supplies			[V		Properly Cleaned				V
TO THE RESERVE AND A SECOND SE		40000000			In Good Repair(Mechanical & Electrical)				V
Penning with the second) () ()	/era	ll So	cho	ol Site Condition:	(نفق		[V]	

School Site: Finance Office Date Inspected Feb 4, 2011

Inspected By Julie Hinds

Main Entrance	U	N	s	E	Classrooms	U	N	S	E
Appearance	(6:09)		\square		Dust/Cobwebs				(ica)
Dust/Cobwebs		\mathbf{Z}	(ske		Doors and Facing			وقييط	(<u>asa</u>)
					Floors and Waste Basket				()
Restrooms	U	N	S	E	Restrooms (cont'd)	U	N	s	E
Floors Cleaned and Disinfected		(e.j.s)	\mathbf{Z}	ونيين	Doors cleaned	(Sa)			(,,)
Ceiling and walls free from debris			Ø		Mirrors cleaned			Ø	(سفید)
Soap, toilet paper and paper towels re-supplied			Ø	الق	Graffiti removed				(<u>L</u>
Trash containers emptied and cleaned			Ø	(E)	Chrome or stainless steel polished		<u> </u>	W	
Sinks cleaned			X)		Walls and partitions cleaned		(m)		(wa)
Toilets cleaned			\square		All surface areas dusted		Z		
Urinals cleaned									
PROCESSOR CONTRACTOR OF STATE OF STATE CONTRACTOR STATE OF STATE CONTRACTOR OF STATE		ļ			O. S. L. M.				
Gym Floors	U		S	E	Cafeteria/Kitchen	U	N	S	E
TO STORE TO THE PROPERTY OF TH					Tables Floors				
Doors, Facings & Windows Appearance					Trash Containers				i
Dust/Cobwebs					Doors, Facings & Windows				
DUSTI OODWOOD				(659)	Appearance				
***	ļ				Dust/Cobwebs				
The state of the control of the state of the	<u> </u>		ļ		The state of the s	(6000)	(Geib)	(668)	(See 2)
Grounds	U	N	S	E	General	U	N	S	E
Appearance			V		Graffiti				
Flower Beds					Drinking Fountains			(LES)	
Litter					Mechanical/Electrical Rooms Orderly				
Supplies		N	S	E	Custodial Equipment	U	N	6	
The state of the s		114	3		the control of the co	U	14	S	E
Cleanliness, organization & supply of custodial room		-			Stored Correctly				last/
Control of Supplies					Properly Cleaned	(Elips	List S		
		The Contract of the Contract o	The state of the s		In Good Repair(Mechanical & Electrical)				(a)
	Ov	'era	ll So	cho	ol Site Condition:				

School Site: Food Service

Date Inspected: 1-6-11 Inspected By: Trent Pannell

•	ī !								
Main Entrance	U	N	S	i	Classrooms	U	N	S	E
Appearance	تغيوا	(Z)	W	E SE	Dust/Cobwebs			X	
Dust/Cobwebs					Doors and Facing	(ENTE)	Ø		
in the American control of the second control of the american control of the cont				استنا	Floors and Waste Basket			V	()
Restrooms	U	N	S	E	Restrooms (cont'd)	U	N	S	E
Floors Cleaned and Disinfected		Ø	(ma)		Doors cleaned				
Ceiling and walls free from debris			Ø		Mirrors cleaned		V		
Soap, toilet paper and paper towels re-supplied			Ø		Graffiti removed			Ø	
Trash containers emptied and cleaned	(E)		Ø		Chrome or stainless steel polished		Ø	(d	
Sinks cleaned			V		Walls and partitions cleaned			$\langle \mathbf{V} \rangle$	
Toilets cleaned			\mathbf{V}		All surface areas dusted		\square		
Urinals cleaned			S						
Company of the Artistance of t					0.5.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.				.,
Gym	U	N	S	E	Cafeteria/Kitchen	U	N	. = -: :	E
Floors				Barrell	Tables				
Doors, Facings & Windows				1	Floors				
Appearance					Trash Containers				
Dust/Cobwebs					Doors, Facings & Windows				
P . Committee State Committee Commit	ļ		 		Appearance				
The second secon			ļ		Dust/Cobwebs		See		النيا
Grounds	U	N	S	E	General	U	N	s	E
Appearance			W		Graffiti		(Fig.)	Ø	
Flower Beds			V		Drinking Fountains		674	V	
Litter			\mathbf{Z}		Mechanical/Electrical Rooms Orderly			N.	
Supplies	U	N	S	Ε	Custodial Equipment	U	N	S	E
Cleanliness, organization & supply of custodial room			N N		Stored Correctly	1		V	
Control of Supplies			(Z)		Properly Cleaned			(A)	(===
e de la companya del la companya de la companya del la companya de		Edwards Arrest	March Association of College		In Good Repair(Mechanical & Electrical)			Ø	
Pic (1923年) 1977年 1977年 1978年 19		da es					ļ	PRESE	() () () () () () () ()
	Ov	era	II S	cho	ol Site Condition:	e de	وتنت	N.	<u>. ie</u>

Site Location Maintenance Date Inspected 1/25/11

Inspected By Marvin Nickels

Main Entrance	U	N	S	E	Classrooms	U	N	s i	=
Appearance					Dust/Cobwebs				(E.S)
Dust/Cobwebs			V		Doors and Facing			وبين	
and the state of t		(sau)		<u> </u>	Floors and Waste Basket		(ELL)		
Restrooms	U	N	S	Ε	Restrooms (cont'd)	U	N	S	E.
Floors Cleaned and Disinfected			\square		Doors cleaned	64	(F.64)	\square	
Ceiling and walls free from debris			V		Mirrors cleaned			V	
Soap, toilet paper and paper towels re-supplied				Z	Graffiti removed		فنعا	(See	Ø
Trash containers emptied and cleaned				Ø	Chrome or stainless steel polished			(406)	\mathbf{V}
Sinks cleaned	أفاعا		V		Walls and partitions cleaned	(W) 16	(e) I		\mathbf{Z}
Toilets cleaned			القليق	V	All surface areas dusted			\square	
Urinals cleaned		(tri	Z	(a)					s are a co
and the second of the second common and the second common terms of the second common and			<u></u>		10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -				
Gym			-	E	Cafeteria/Kitchen				E
Floors					Tables			Ø	
Doors, Facings & Windows		1			Floors				
Appearance				لسا	Trash Containers				$\overline{\mathbf{A}}$
Dust/Cobwebs					Doors, Facings & Windows			V	
	ļ				Appearance				
	ļ		!		Dust/Cobwebs			Z	
Grounds	U	N	s	E	General	U	N	S	E
Appearance		(E39)	N		Graffiti			8173	V
Flower Beds				V	Drinking Fountains				V
Litter				V	Mechanical/Electrical Rooms Orderly				(V)
Supplies	U	N	s	E	Custodial Equipment	U	N	S	E
Cleanliness, organization & supply of custodial room				Z	Stored Correctly		(34)		V
Control of Supplies			(LEE	\mathbf{V}	Properly Cleaned			(EE)	V
The control of the co		-	ann ideal defended a con-		In Good Repair(Mechanical & Electrical)				V

School Site: Student Services

Date Inspected: 1-6-11 Inspected By: Trent Pannell

Main Entrance	U	N	s	E	Classrooms	UNS	E
Appearance			Z		Dust/Cobwebs		
Dust/Cobwebs					Doors and Facing		(max)
er is mer er fra somsåfer no er staddingster vir allkaldstadda saksaats och i da er viviser i saks					Floors and Waste Basket		(41.6)
Restrooms	U	N	s	E	Restrooms (cont'd)	UNS	E
Floors Cleaned and Disinfected					Doors cleaned		
Ceiling and walls free from debris			Z		Mirrors cleaned		
Soap, toilet paper and paper towels re-supplied		(ing)	V		Graffiti removed		(₄₂)
Trash containers emptied and cleaned			Ø		Chrome or stainless steel polished		
Sinks cleaned			V		Walls and partitions cleaned		[V]
Toilets cleaned			V		All surface areas dusted		
Urinals cleaned			Ø			_	,
Gym	U	N	s	E	Cafeteria/Kitchen	UNS	E
Floors			V		Tables		
Doors, Facings & Windows			(Z)	22	Floors		
Appearance			(V)		Trash Containers		
Dust/Cobwebs				V	Doors, Facings & Windows		
				_	Appearance		
Fig. 18 Co. St. 1990 F. STROTTE CONSISTANCE ON TO SERVICE MESSAGE AND ASSAGE AND ASSAGE PERSONS ASSAGE AND ASSAGRATION ASSAGRATION ASSAGE AND ASSAGE AND ASSAGE AND ASSAGE AND ASSAGRATION ASSAGRA	-		ļ		Dust/Cobwebs		
Grounds	U	N	s	E	General	UNS	E
Appearance					Graffiti		(E)
Flower Beds			(X)	GAG	Drinking Fountains		[inject]
Litter		W			Mechanical/Electrical Rooms Orderly		
Supplies	U	N	S	E	Custodial Equipment	UNS	E
Cleanliness, organization & supply of custodial room			V		Stored Correctly		(دفق
Control of Supplies			$ \mathbf{Z} $		Properly Cleaned		
		A VALUE OF THE PROPERTY AND ADDRESS OF THE PERSON AS A	***************************************		In Good Repair(Mechanical & Electrical)		
	Ov	/era	II S	cho	ol Site Condition:		

School Site: Technology

Date Inspected: 1-6-11 Inspected By: Trent Pannell

Main Entrance	U	N	s	E	Classrooms	U	N	s	E
Appearance	(Also		\mathbf{V}		Dust/Cobwebs				
Dust/Cobwebs			V		Doors and Facing	~ .		\mathbf{Z}	
				(E)	Floors and Waste Basket			\mathbf{V}	
The state of the s			_						
Restrooms	U	N	S	1772	Restrooms (cont'd)	U	N	S	E
Floors Cleaned and Disinfected			Ø		Doors cleaned		(mp)	\square	لت
Ceiling and walls free from debris			Ø	Estate 1	Mirrors cleaned			(V)	
Soap, toilet paper and paper towels re-supplied			Ø		Graffiti removed		()	Ø	
Trash containers emptied and cleaned			Z		Chrome or stainless steel polished	(e.s)	Ø		
Sinks cleaned			V	(E-3)	Walls and partitions cleaned			\mathbf{V}	
Toilets cleaned	(E)		√		All surface areas dusted			N	
Urinals cleaned			V						
The state of the s				<u> </u>	The second secon				_
Gym	U	N	S	E	Cafeteria/Kitchen	U	N	S	E
Floors			V		Tables				
Doors, Facings & Windows				-	Floors		1	V	1
Appearance			N.		Trash Containers				
Dust/Cobwebs			W	[Ess]	Doors, Facings & Windows				
	ļ		<u> </u>	ļ	Appearance		1		
The state of the control of the cont				ļa.	Dust/Cobwebs			N.	
Grounds	U	N	S	E	General	U	N	S	E
Appearance	(E)		V		Graffiti			V	
Flower Beds			(V)		Drinking Fountains	(East)	(e)	V	
Litter			W		Mechanical/Electrical Rooms Orderly			2 amount	
Supplies	U	N	S	E	Custodial Equipment	U	N	S	E
Cleanliness, organization & supply of custodial room		Ø	(MG)		Stored Correctly	(si	(mile)		
Control of Supplies			V		Properly Cleaned				
		d house of the same			In Good Repair(Mechanical & Electrical)		E	V	
	į Vietora	and the same of th	1				n seen	1710/1250	Description of
	O۱	era	II S	cho	ol Site Condition:	grap.	12.3	V	

School Site:

Transportation Bus Shop

Date inspected Feb 4, 2011

Inspected By: Marvin Nickels

U Unsatisfactory

N Needs Improvement S Satisfactory E Exceeds Standards

Main Entrance	U	N	s	E	Classrooms	U	N	S	E
Appearance	انتيدا	(via)	\mathbf{Z}	(kaid	Dust/Cobwebs				(i.i.)
Dust/Cobwebs	E S	\square	(As	(<u>60</u>)	Doors and Facing				
					Floors and Waste Basket		(1887)	•	
Restrooms	U	N	s	E	Restrooms (cont'd)	U	Ν	S	E
Floors Cleaned and Disinfected				64	Doors cleaned				
Ceiling and walls free from debris			Ø		Mirrors cleaned				
Soap, toilet paper and paper towels re-supplied			Ø		Graffiti removed				(<u>V</u>)
Trash containers emptied and cleaned				Z	Chrome or stainless steel polished		Ø	wid)	
Sinks cleaned		}	V	t	Walls and partitions cleaned			\square	
Toilets cleaned			N.		All surface areas dusted			W	
Urinals cleaned			Ø					ļ	
Gym	U	N	S	E	Cafeteria/Kitchen	U	N	s	E
Floors					Tables				E. ji
Doors, Facings & Windows					Floors				
Appearance					Trash Containers				
Dust/Cobwebs					Doors, Facings & Windows				
ti se e e e e e e e e e e e e e e e e e e	ļ		, , ,	ļ	Appearance				
The interest entering a continue with an administration for the continue of th	ļ,	ļ.,,,,,,	part of t		Dust/Cobwebs	(Life)	(E.J.)		1 (a.s.)
Grounds	U	N	s	E	General	U	N	s	E
Appearance			W)	ļ	Graffiti			-	W)
Flower Beds	1	(((((((((((((((((((1	Drinking Fountains			100	
Litter		·	-	A	Mechanical/Electrical Rooms Orderly	+==			3
Supplies	U	N	S	E	Custodial Equipment	U	N	S	E
Cleanliness, organization & supply of custodial room			Z		Stored Correctly				
Control of Supplies					Properly Cleaned				
the state of the s			maniference in the same sayable		In Good Repair(Mechanical & Electrical)	la la		Ø	
	O۷	/era	II S	cho	ol Site Condition:) []	