

Wisconsin Department of Public Instruction SCHOOL BUS ACCIDENT REPORT s. 121.53(6) PI-3110 (Rev.12-11) INSTRUCTIONS: Complete both sides and return to appropriate school board.

Section 121.53(6) of the Wisconsin Statutes reads as follows: "Within 10 days after its occurrence, every accident involving a motor vehicle providing transportation under this subchapter shall be reported to the appropriate school board.

transportation under this s	ubchapter shall be reported to the	e appropriate s	chool board.			
		GENERAL II	NFORMATION			
School		School Distric	School Code			
Bus Owner First Studen	t, Inc.	Address of Owner, Street, City, State, Zip 6206 Alderson St, Weston, WI 54476				
Chassis Make IC		Model Year 2002	Body Make IC3S5		Student Capacity 71	
		DRIVER INI	FORMATION		I	
Name of Driver Sandra I	_ange		Sex Male X Female	Age 57	Years of Experience as Bus Driver 1.5 years	
Has your driver had the rec	ommended training in first aid?	When did driv	er last attend a state-sponsored	bus driver training :	session? N/A	
X Yes 🔲 No						
		ACCIDENT D	ESCRIPTION			
Date of Accident	Time 3:15	Location of Ac	ccident Jelinek Ave & Busines	s 51		
09/08/14	Хрм			•	•	
Weather Conditions Clea	ar / Dry	L	Type of Road and General Cor	nditions Asphalt /	Dry	
Speed of Bus	Speed of Other Vehicle(s)	Was a Citation	n Issued?			
0 MPH	Unknown	☐ No	X Yes If yes, to whom? Th	ne other driver was d	cited.	
If no citation was issued, wh	no, in your opinion was responsib	ole for the accid	lent and why?			
prevented the collision. The	sponsible, could she/he have p other party's vehicle rear ended to the left of the bus. There was	I the bus while i	it was stopped in traffic. The bu	s was blocked in by	buses in front of it and	
	ults of the accident in detail. <i>Iten</i> s damage to the rear bumper ar					
Ware there students in the h	ue of the time of the pesident?	Т	How did students ovit? Check a	II that apply		
Were there students in the bus at the time of the accident? No—If no, skip next two questions			How did students exit? Check all that apply. X Front Door Rear Door Windows Didn't Exit			
X Yes—If ves. complete all questions			Other			

Page 2				PI-3110	
Had the riders been instructed and drilled in bus evacuation/emergency exits?			Was a first aid kit used?		
X Yes 🔲 No	☐ Yes	X No	☐ Yes	X No	
	INJURIES/	ATALITIES			
Names of Students Injure	ed		Nature of Injurie	98	
N/A					
Names of Other People Inju	Nature of Injuries				
N/A					
	PROPERT	/ DAMAGE			
Describe Damage to School Bus - The rear bump be replaced.	per was scratched and de	ented. The exha	ust pipe was damaged and h	ad to Estimated Repair Cost \$ 187.75	
Describe Damage to Property of Others - The oth and etc.	er vehicle had damage to	the front bump	er, hood, engine, light asseml	olies, Estimated Repair Cost \$Unknown	
	RECOMME	NDATIONS		<u> </u>	
As a result of this accident, what suggestions do yo	ou have to offer for the im	provement of the	following:		
Bus Safety Regulations or Laws N/A					
School Bus Standards N/A					
Bus Driver Training N/A					
	CERTIFI	CATION			
If an accident results in injury to or death of any per the local or state enforcement officer [Wisconsin St	atute 346.70(1)] and the	Department of Tr	ansportation [Wisconsin Stat	ute 346.70(2)].	
I CERTIFY that this accident has been reported to t	· · · · · · · · · · · · · · · · · · ·	nent officer and t	7		
Name of Persons Completing Form Kevin M. Mi	litel		Position First Student Lo	Cation Ivianager	
Signature M. Muli			de constant de la con	Date Signed <i>Mo./Day/Yr.</i> 09/09/2014	