

NUMBER	COLOR	YEAR	MAKE/MODEL	License Plate	MILAGE	Driver	Comments
LM #2	Red	2000	Ford F-350 4x4	C15404	147,359	Shanna	Heater barely works
LM #3	White	2014	Chevy Express Van	C21373	91,862	Ken	
LM #4	White	2015	Chevy Express Van	C21621	75,004	Chris	
LM #5	White	2016	GMC Savana Van	C21622	109,915	Jon	
LM#6	White	2017	Chevy Express Van	C00858	69,371	David	
LM#7	White	2014	Ford 2500 Van	C01010	82,710	Shane	
LM#8	white	2015	GMC Savana Van 2500	C01124	56,535	Josh	
LM#14	Yellow	1971	John Deere 4x4 Loader				
LM #16	Silver	1981	Ford 2 ton Dump truck	C10091	98,447		
LM#19	White	1995	Chevy 1 ton 4x4	C8091	354,339	Trash truck	Exhaust leaks through holes in floorboard
LM #21	Blue/White	1980	Ford tractor				
LM #29	Yellow	1988	JCB Backhoe				
LM #30	Blue-Green	1998	GMC 3/4 ton 4x4	C13481	296,519	Shawn	
LM #32	Beige	1999	Olds 88DE	C12594			
LM #35	Green Letters	2005	GMC VN SAV	C16173	204,551	Technology	Lift gate does not work properly
LM #36	Blue Letters	2005	GMC VN SAV	C16430	177,740		
LM #39	Green	2006	Dodge Caravan	C16945	196,061	Old Mail Van	Ready for disposal
LM#39 new	White	2025	Honda Odyssey	C03843	790	Courtney	
LM #40	Grey	2010	Chevy 3/4 ton HD 4x4	C16946	183,778	Tim	Needs engine work
LM #41	Black	2004	Dodge 3/4 ton X-Cab 4x4	C17097	191,211	Joe	
LM #42	White	2003	Ford F-350 4x4	C18116	192,190	Adam	
LM #43	Blue/Grey	1989	Chevy 1-ton	C19996	202,092		Blown Motor Ready for disposal
Skid	Yellow		Gehl R190		2301.2 hours		
Scissor Lift	White/Orange	2003	JLG 2632E2				Controler needs fixed
Man Lift	Orange	2015	JLG 340AJ		1751 hours		