

Insp. No.:	44718		
File No.:	ED-2683-1		
Insp. Date:	02-Feb-16		
Insp. Time:	2.00	Travel:	3.25
Inspector:	Kastella, Kurt W		
Occupied:	<input checked="" type="checkbox"/>		
*Recommendations:	<input type="checkbox"/>		

State Fire Marshal Division
 Minnesota Department of Public Safety
 444 Cedar St., Suite 145
 St. Paul, MN 55101-5145



Inspection and Compliance Orders

Property:

Middle River Community School

Fourth St, PO Box 130
 Middle River, MN 56737

Contact: Contact Name/Phone: Dale Wiskow - Maint Tom Jerome - Superintendent 218-222-3310
 Contact E-mail: sschultz@greenbush.k12.mn.us
 Property Phone: 218-222-3310

Owner:

Greenbush-Middle River School District 2683

Box 70
 Greenbush, MN 567260070

Contact: Contact Name/Phone: Tom Jerome - Superintendent
 Contact E-mail: tjerome@greenbush.k12.mn.us
 Owner Phone: 218-782-2231

Agency Req.: Scheduled: Complaint: Permit/Plan Review: Owner Requested: Inspector Initiated: Consultation:

Item #	Ref #	Code	Section	Days to Correct	Violation	Remarks
1	972	MSFC 2007	1019.3	60	Ensure that exits are continuous from the point of entry into the exit to the exit discharge.	Discontinue the use of the back room 61 for students us. The students must pass through two storage rooms to exit from this room
2	778	MSFC 2007	408.3	90	Provide fire evacuation drills in compliance with the following: 1. First drill within 10 days of school start, 2. Time of day to vary, 3. Assembly points to be a safe distance from school building (at least 50 feet), 4. Accountability of students must be provided.	No fire drill documentation for 2014-15 school year
3	872	MSFC 2007	901.10	90	In buildings protected by automatic sprinklers or automatic fire detectors, suspended or removable ceiling tiles shall be maintained in place to prevent the delay in sprinkler or detector activation.	Replace the damaged ceiling tile in resource room

Inspection Remarks:
 This was the 2015-2016 Interval Inspection of this 44,459 sq. ft. educational building for School District ISD 2683. NOTES:
When the above orders have been corrected contact this DSFM to arrange for a Follow-up Inspection.

Owner/Representative:	Dale Wiskow (Maintenance)
Inspector:	Kurt Kastella (Deputy State Fire Marshal) 651-769-7775

A variance procedure is available. Please contact the inspector named for further assistance with this or any other matter.

* Items that are a result of a recommendation do not require days to correct.