

## Wisconsin Department of Public Instruction SCHOOL BUS ACCIDENT REPORT s. 121.53(6) PI-3110 (Rev.12-11)

**INSTRUCTIONS:** Complete both sides and return to appropriate school board.

Section 121.53(6) of the Wisconsin Statutes reads as follows: "Within 10 days after its occurrence, every accident involving a motor vehicle providing transportation under this subchapter shall be reported to the appropriate school board.

		GENERAL IN	FORMATION			
School: DC Everest Middle School		School District: DC Everest School District			School Code: 4970	
Bus Owner: Lamers Bus Lines		Address of Owner, Street, City, State, Zip: 3805 Concord Ave, Weston WI 54776				
Chassis Make: Blue Bird		Model Year: 2017	Body Make: Conventional propane		Student Capacity: 77	
		DRIVER INF	ORMATION			
Name of Driver: Nathan Schultz			Sex X Male Female	Age: 46	Years of Experience as Bus Driver: 2 Years 7 Months	
Has your driverhad the reco	ommended training in firstald?	When did dr	iver last attend a state-spon	sored bus driver	training session? NA	
			DESCRIPTION			
Date of Accident: 11/24/25	Time 2:43 pm	Location of	Accident 6507 County Rd J	– Weston		
Weather Conditions: Clou	dy	<u> </u>	Type of Road and General Conditions – Two lane Hwy – straight			
Speed of Bus:	Speed of Other Vehicle(s):	Was a Citati	on Issued? No: X Yes If	es, to whom?		
Approximately 1-2 MPH	0 MPH					

If no citation was issued, who, in your opinion, was responsible for the accident and why? Our driver was traveling southbound on Co Hwy J – a fight broke out between 2 boys on the bus. The driver looked up in his student mirror and then back to the road. The car was stopped in front of the bus–Our driver tapped the back of the car that was waiting to turn left into Dollar General.

If driver was not legally responsible, could she/he have prevented the accident by driving defensively? Explain – Driver could have continued to watch the road in front of him to find a place to drive to to pull over.

Describe the cause and results of the accident in detail. Itemize injuries and property damage on reverse: A fight in the back of the bus caused the driver to become distracted by looking in his student mirror to see what was happening. When the driver looked at the road there was a car stopped attempting to make a left turn into Dollar General. The driver pressed on the brakes to stop and tapped the back of the other vehicle.

Front Door X  Other	ts exit? <i>Check all that apply.</i> Rear Door 🔲 Wind	dows Didn't Exit:		
her used?	Was a first aid kit used	1?		
X No	☐ Yes	X No		
S/FATALITIES				
Names of Students Injured Nature of Injuries				
NA		·		
Nature of Injuries				
NA	· · · · · · · · · · · · · · · · · · ·			
RTY DAMAGE				
Describe Damage to School Bus: School bus has a bent license plate				
Describe Damage to Property of Others: the other car had an approximately 3 inch scratch on the bottom of the back bun and the chrome trim piece above the bumper was cracked.				
MENDATIONS				
r the improvement o	f the following?			
• *				
	•			
naging students.				
naging students.				
naging students.				
าสถากกร	tuuoitto.	idusitio.		

PI-0000 Page 3 I CERTIFY that this accident has been reported to the local or state enforcement officer and to the Department of Transportation, if required by law. Name of Persons Completing Form: Wendi DeMars Position: Weston Location Manager

Signature

Date Signed Mo./Day/Yr. 11/25/2025