

Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER Pana Community Unit School District No. 8	COUNTY Christian/Montgomery
FACILITY NAME Junior High School	FACILITY LOCATION 203 West 8th Street, Pana

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 01/10/2023 by Dean Keller.

Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
12	Administration and General	Was completed, report unavailable
14	Administration and General	Storage height should be 24" below ceiling (18 in sprinkled areas),
25	Administration and General	Kitchen sink outlet needs gfi, wood shop outlets have been taped over needs cover, beef rm needs gfi, exposed electrical wire science room demo desk,
26	Administration and General	Greenhouse needs CO,
70	Boiler Room	Furnace in girls locker room needs separation.
111	Corridors	Light by library doesn't appear to work.
122	Elevator and Conveying Systems	Certificate applied for not received
161	Industrial Technology Labs	Remove grill with propane tank.
276	Stairwells	Remove storage from stage stairs (NW),