

FACILITIES/CONSTRUCTION REPORT

JULY 2025

BHS HVAC:

- 7-7 Calm, hot@78 degrees. KQC Roofing waterproof the AC support units, 1 worker.
- 7-8 Calm, hot@82 degrees. KQC Roofing waterproof the AC support units, 1 worker. Sletten patch/sand sheetrock results of water damage C wing, 2 workers.
- 7-9 Breezy, hot@80 degrees. KQC Roofing waterproof the AC support units , 1 worker. Sletten patch/sand sheetrock results of water damage C wing, 2 workers.
- 7-14 Calm, warm@64 degrees. Heartland Mechanical install piping for AC units, 2 workers.
- 7-15 Rain, warm@60 degrees. Heartland Mechanical install piping for AC units, 2 workers.
- 7-16 Calm, warm@66 degrees. Sletten replace ceiling tiles and cutout for sprinklers, cameras and vents, 3 workers. Heartland Mechanical install piping for AC units, 2 workers.
- 7-17 Calm, warm@68 degrees. Sletten replace ceiling tiles and cutout for sprinklers, cameras and vents, 3 workers. Heartland Mechanical install piping for AC units, 2 workers.
- 7-22 Rain, warm@60 degrees. Littrell Electric locate power sources for AC units, 1 worker.
- 7-23 Calm, warm@70 degrees. Littrell Electric run conduit from power source to AC units, 1 worker.
- 7-24 Breezy, warm@74 degrees. Littrell Electric run conduit from power source to AC units, 1 worker.
- 7-30 Calm, hot@80 degrees. Heartland Mechanical install piping for AC units, 2 workers. Littrell Electric run conduit from power source to AC units, 1 worker.
- 7-31 Calm, hot@80 degrees. Heartland Mechanical install piping for AC units, 2 workers. Littrell Electric run conduit from power source to AC units, 1 worker.