GRANBY PUBLIC SCHOOLS: INDOOR AIR QUALITY REPORT

PRESENTED BY


SHANNON SULLIVAN

DIRECTOR OF FACILITIES





RESPONSES TO THE SURVEY:




GENERAL CLEANLINESS

Question	Yes	No	N/A	Totals
General Cleanliness: Classroom is clean	36	0	0	36
General Cleanliness: Classroom is dusted and vacuumed	20	4	2	
thoroughly and regularly	30			36
General Cleanliness: Trash is removed daily	34	2	0	36
General Cleanliness: Room is free of pests	23	13	0	36
General Cleanliness: Spills cleaned	35	1	0	36






DRAIN TRAPS & MOISTURE IN CLASSROOM




Question	Yes	No	N/A	Totals
Drain Traps in the Classroom: Odor coming from classroom drains (toilets/sinks)	3	15	18	36
Moisture in the Classroom: Windows, window sills, and window frames free of condensate	33	2	1	36
Moisture in the Classroom: Indoor surfaces of exterior walls free of condensate	34	2	0	36
Moisture in the Classroom: Found leaks or signs of moisture (sink, ceiling tiles, lavatories)	10	22	4	36

THERMAL COMFORT, VENTILATION, & EXHAUST FANS



	-			
Question	Yes	No	N/A	Totals
Thermal Comfort: No signs of draftiness	23	11	2	36
Thermal Comfort: Room usually comfortable	22	13	1	36
Thermal Comfort: Need help, room frequently uncomfortable	15	18	3	36
Ventilation: Windows are operable	30	3	3	36
Ventilation: Need help, sometimes smell unexplained or unpleasant orders in classroom	3	32	1	36
Local Exhaust Fans: Fan and fume hoods are used properly	7	0	29	36





ART SUPPLIES & ATHLETICS

Question	Yes	No	N/A	Totals
Art Supplies: Following good handling and storage practices	0	0	7	7
Athletics: Locker room and showers cleaned regularly and properly	1	1	5	7
Athletics: Soiled clothes and towels are removed regularly	0	1	6	7









SCIENCE SUPPLIES

Question	Yes	No	N/A	Totals
Science Supplies: SDS on hand	4	0	6	10
Science Supplies: Spill procedures in place	4	0	5	9
Science Supplies: All chemicals are labeled accurately	4	0	5	9
Science Supplies: Supplies stored according to manufacturers' recommendations	4	0	5	9
Science Supplies: Recommend procedures for disposal of used substances understood and followed	4	0	5	9
Science Supplies: Compressed gas cylinders secured	2	0	7	9
Science Supplies: Storage areas separate from main classroom	4	0	5	9
Science Supplies: Diluted substances rather than concentrates used whenever possible	3	0	6	9
Science Supplies: Fume hoods capture respirable particles, gases, and vapors released within them	1	0	8	9




T		· · · · · · · · · · · · · · · · · · ·				
Question	Yes	No	N/A	Totals		
Industrial and Vocational Education Supplies: SDS on Hand	0	1	6	7		
Industrial and Vocational Education Supplies: Spill procedures in	4	0	_			
place.	1	U	6	7		
Industrial and Vocational Education Supplies: Supplies stored	0	0 0	0 6			
according to manufacturers' recommendations	0	U	6	6		
Industrial and Vocational Education Supplies: Recommend	0		0 6			
procedures for disposal of used substances understood and		0				
followed				6		
Industrial and Vocational Education Supplies: Compressed gas		0	0	0 0 6		
cylinders secured	O		0	6		
Industrial and Vocational Education Supplies: Storage areas	0	0	0 6			
separate from main classroom	0		6	6		
Industrial and Vocational Education Supplies: Fume hoods						
capture respirable particles, gases, and vapors released within	0	0	6			
them					6	







COMMENTS ON THE SURVEY



- THIS YEAR IN LEU OF COMMENTS WE ASKED STAFF MEMBERS
 - IF THEY RESPONDED 'NO' TO ANY OF THE QUESTIONS IF THEY <u>WOULD</u> OPEN A WORK ORDER IN THE NEXT 30 DAYS SO THE ISSUE CAN BE ADDRESSED
 - 17 RESPONDED YES TO THIS QUESTION, BUT ONLY 2 WORK ORDERS WERE OPENED, ADDRESSED, AND CLOSED BY THE MAINTENANCE DEPARTMENT
 - THE OTHER OPTION PROVIDED TO STAFF MEMBERS WAS I **DO NOT** PLAN ON OPENING A WORK ORDER
- THE SURVEY RESULTS WERE ANALYZED DECEMBER 5TH 2022 AND AS OF JANUARY 6TH ONLY (2)

 WORK ORDERS WERE OPENED TO ADDRESS ANY OF THE ISSUES SURVEY PARTICIPANTS
 REPORTED.

WORKORDERS GENERATED FROM THE SURVEY:

- WORKORDER# 56242 LEAK IN THE CEILING NEAR THE ENTRANCE DOOR TO THE CLASSROOM, RIGHT ABOVE THE SMALL AMERICAN FLAG IN THE CORNER. THERE WAS A DECENT AMOUNT OF WATER THAT POOLED UP ON THE FLOOR TWO DAYS AGO WHEN WE HAD HEAVY RAIN.
- WORKORDER# 56592 THE WINDOW CRANK WILL NOT TURN. THE WINDOW OPENS JUST A
 CRACK, AND THEN IT WILL NOT MOVE ENOUGH TO SHUT AND LATCH THE WINDOW FULLY. IT
 IS CURRENTLY NOT COMPLETELY CLOSED AND LEAKING COLD AIR IN.
- MAINTENANCE REPAIRED THESE ITEMS WITHIN A DAY OF THE ISSUE BEING REPORTED.





GUEST SPEAKER: MR. KEVIN BOGUE



Platform Environmental, LLC

Licenses to serve our clients ...

- Licensed Environmental Professional (LEP)
- Certified Hazardous Materials Manager (CHMM)
- · Connecticut Asbestos Inspector/Management Planner
- Connecticut Asbestos Project Designer

- Certified Industrial Hygienist (CIH)
- Professional Geologist (PG)
- Connecticut Asbestos Project Monitor
- Connecticut Lead Inspector/Risk Assessor





