

# Field Notice of Violations/Unsafe Conditions

DISTRICT NAME AND NUMBER Meridian CUSD 223	COUNTY Ogle
FACILITY NAME Stillman Valley High School	FACILITY LOCATION 425 S Pine St, Stillman Valley

Potential problems or violations of the Health Life/Safety Code for Public Schools (23 Illinois Administrative Code Part 180) as noted below were discovered in the course of the annual inspection of the above named facility conducted on 10/24/2024 by Josh Knuth.

**Please respond within 10 days by describing the corrective action to be taken in the shaded space provided below, for each item listed. An annual inspection report summarizing your progress regarding the corrections will be submitted through IWAS on or before July 30th.**

GLOSSARY NUMBER	LOCATION (Fire Area, Floor, Room Number)	DESCRIPTION OF PROBLEM
4	Administration and General	Hold-open devices on wood shop storage doors, room 106 and 126; throughout building
5	Administration and General	Wrestling exit blocked; corridor doors by kitchen blocked with chain; room 106 has security lock engaged; egress blocked to exit room 18; gym doors by E; corridor behind gym
6	Administration and General	Exit sign in greenhouse
12	Administration and General	Repair deficiencies noted on the annual alarm system report
13	Administration and General	Repair deficiencies noted on the annual sprinkler system report
14	Administration and General	Clearance to ceiling needed in rooms 109, 110 storage room, library storage, band storage, 113, 115, 119, 120 and 131
16	Administration and General	Extinguisher blocked in main office closets; extinguisher needed in press box; mount extinguisher in welding area
22	Administration and General	Fire rating needed on chair in rooms 114 and 120
23	Administration and General	Ceiling tile in IT closet main office, room 131, gym entrance and door H; wrestling room loft needs to be dry walled so that exposed wood is not showing; band storage has autistic foam that is not needed anymore-remove or provide flame-proofing documentation
24	Administration and General	Extension cord in room 119, 122 and wrestling room; overloaded power strip in room 120
25	Administration and General	Open clock in room 109; overloaded power strip in room 116 and 120; open junction box in wrestling room; light cover in storage room 123; electrical panel blocked room 124, 133 and weight room; GFI needed drinking fountain in corridor behind gym
26	Administration and General	Needed in kitchen and greenhouse
94	Classrooms	Room 104 not latching; doors in non-sprinkled areas must close and latch
112	Corridors	Fire doors by girls' restroom east side
134	Greenhouses	Detection needed
138	Gym and Multipurpose Rooms	Occupant load needed in weight room
143	Gym and Multipurpose Rooms	Wrestling exit needs closer
230	Science Laboratories	Chemical storage cabinets needed in room 124
241	Solar Photovoltaic Power Systems, Roof Mounted	Mark the shutoff
283	Storage/Supply/Closets	Detection needed IT closet main office closets
284	Storage/Supply/Closets	Detection needed in band storage doors

## Field Notice of Violations/Unsafe Conditions

315	Woodworking Shop	Door K needs to latch; storage room doors need to close and latching in
320	Woodworking Shop	Housekeeping needed