

Transportation Report July 2015

1. Bus #33 – DPF serviced. This vehicle is currently in the shop for a/c work
2. Ag truck – Oil change and filter
3. Suburban #7 – Replaced fan assembly
4. Prius #5 – Oil change and filter
5. Prius #6 – Oil change and filter
6. Toro reel mower – serviced reel motor repaired

Fields and Grounds

1. Striped practice field
2. Mowing, mowing, mowing
3. Will be striping the main field on 8/6/2015

Marcus Schwandner
Transportation Director
Fields and Grounds Manager