





OVERALL SITE

|         |
|---------|
| 06/2026 |
| 05/2026 |
| 04/2026 |
| 03/2026 |
| 02/2026 |
| 01/2026 |
| 12/2025 |
| 11/2025 |
| 10/2025 |
| 09/2025 |
| 08/2025 |
| 07/2025 |
| 06/2025 |
| 05/2025 |
| 04/2025 |
| 03/2025 |
| 02/2025 |
| 01/2025 |
| 12/2024 |
| 11/2024 |
| 10/2024 |
| 09/2024 |



SCIENCE LAB



WORKROOM




SECONDARY STAIR

- POWER AND GAS DELIVERED TO SITE
- LANDSCAPING INSTALL BEGAN
- LOCKER INSTALL NEAR COMPLETION
- CASEWORK INSTALL 90% COMPLETE
- CEILING TILE INSTALL TO BEGIN SOON




OVERALL SITE

|         |
|---------|
| 06/2026 |
| 05/2026 |
| 04/2026 |
| 03/2026 |
| 02/2026 |
| 01/2026 |
| 12/2025 |
| 11/2025 |
| 10/2025 |
| 09/2025 |
| 08/2025 |
| 07/2025 |
| 06/2025 |
| 05/2025 |
| 04/2025 |
| 03/2025 |
| 02/2025 |



RECEPTION



CLASSROOM CORRIDOR



TYPICAL CLASSROOM

- 2<sup>ND</sup> FLOOR CLASSROOMS COMPLETE
- VCT INSTALL IN PROGRESS
- WALL TILE INSTALL NEAR COMPLETION
- GYM FLOORING INSTALL TO BEGIN END OF MONTH