# FACILITIES PRIORITY REPORT

# April 2020

Planned Maintenance		Planned Capital Projects		Planned Summer Inspections	
~	MHS Kitchen Water Heater Replacement	~	Boys and Girls Locker Room Water Heater Replacement	~	Fire Alarm/Smoke Detectors Inspections
~	Replace Water Line at MRMS	v	MHS Gym Siding (Portions South and West Side	~	Fire Door Drop Testing
~	MRMS Carpet Rm 18	~	MHS Gym Roofing (Boys Locker RM)	~	Air Handlers (MES&MHS)
~	Reseal & Stripe MES and add 2 speed Bumps (Safety)	~	Mulino Cafeteria	~	Boiler Inspections
~	Reseal & Strip Mulino Bus Lane	~	MES Gutters	~	Elevator Inspection
~	Replace Motor & Bearing Assembly in boiler room at Clarkes	~	Clarkes Siding/Post Repair	~	Lift Inspection
~	Carpet RM 3 at Clarkes			~	Backflow Inspection
				~	HVAC Inspection

# <u>High School</u> –

- Repaired plumbing leak in girl's locker room
- Sprayed for weed control in courtyard
- Repaired door on batting cage (Vandalism)
- Replaced controller on RTU 10
- Repaired water leak in underground vault in front of gym
- Installed pressure relief on wood shop compressor
- Installed new airline retractable hose reel

## Middle School -

- Changed all air filters
- Painted entire cafeteria
- Replaced ballast in cafeteria
- Sanded and prepped bathroom walls for paint

#### Molalla Elementary -

- Replaced faulty switch on dishwasher
- Replaced stained ceiling tile

#### <u>Mulino</u>-

- Painted bollards safety yellow
- Painted doors on S. Building

## Rural Dell –

- Repaired leak on heating unit (Gym)
- Strip and wax gym floor
- Changed air filters

## <u>Clarkes</u> –

- Strip gym floor
- Material testing for seismic upgrades
- Begin removing items from upstairs (seismic upgrade)
- Cleaning out bus barn

# <u>D/0</u>-

- Replaced Flush-o-meter in men's urinal
- Sanitized, knobs, surfaces, etc. (daily)

## **District Wide**

• Summer inspection on all HVAC

Middle School Painting Projects





