

HENSON ROBINSON COMPANY

3550 GREAT NORTHERN AVE., 62711
P.O. BOX 13137
SPRINGFIELD, IL 62791



TELEPHONE: 217-544-8451
FAX: 217-544-0829
www.hensonrobinson.com

February 24, 2021

Pana HS Valley Repair

Attn: Ryan Benson

Please consider our proposal for the above captioned project as per your request.
We include labor and material to perform the following scope of work:

- Install coating and fabric per manufacturer's recommendations to seal valleys (~200' total)
- Replace worn out pipe boots throughout roof (10 EA)


We also include freight, delivery, hoisting, safety, and clean-up of our work site.

Proposal as stated above: \$18,891 *Eighteen thousand eight hundred ninety-one dollars.*

Exclusions: Premium time

Sincerely,

Charlie Randles



PHS

201 W. 8th Street
Pana, IL 62557

W 8th St

Sect. 7

Sect. 6

Sect. 2

Sect. 1

Sect. 3

Sect. 5

Sect. 4

Legend



200 ft

100 Lineal Feet

93 Lineal Feet

Google Earth

© 2020 Google



Photo Report

Client: Pana CUSD #4

Facility: Pana High School

Other: Damaged Valleys

Report Date: 12/04/2020

Title: Valley Damage Report



Photo 1

Leaks in the Gym are coming from the damaged valley.



Photo 2

Valley had been repaired with peel and stick EPDM in the past.



Photo 3




Photo 4

Rusted valley and end of panel. The EPDM actually trapped moisture causing the panels and valley closure to rust.



Photo 5



Photo 6

Valley is very rusted in areas.



Photo 7