

## 7/28/2022

Alpena County Health Department Attn: Mike Desmond 100 Woods Circle Alpena, MI 49707

Project: Compressor Replacement Quote

Location: Alpena, MI

Control Solutions, Inc. to provide labor and material to replace the failed Trane compressor on the first-floor condenser, stage 2.

Our price includes:

## **Equipment Controlled/Monitored:**

1rst Floor Condenser

## Including:

- 1 Trane compressor, fan, and motor
- Installation labor and material
- System Start-up and Check-out
- One Year Parts and Installation Warranty

Total Sum: \$8623.00

## Assumptions and/or Exceptions:

- All programming by Control Solutions, Inc.
- No allowance to replace faulty devices within the programming portion of the project.
- · No allowance to repair faulty HVAC equipment.

Submitted by:

Bill Hafer

Service Sales

Control Solutions, Inc.

1

WWW. CONTROLYOURBUILDING.COM

[989] 379-2404

2284 DIAMOND POINT RD ALPENA, MI 49707