School District Name Buffalo

School District Number 877

*OSHA is citing

Assessment Results/Findings

possible OSHA fines

| Building | Location | Standard | Description | Min | Max |
|----------|---|-------------------------------|---|-----------|------------|
| Buffalo | wood shop | chemical hygiene | Refrigerator cannot hold both food & chem./biological | \$1500.00 | \$2000.00 |
| Buffalo | wood shop | compressed gases | Air nozzle must be reduced to 30 psi | \$500.00 | |
| Buffalo | storage by room C110 | compressed gases | Cylinders not secured | \$500.00 | \$2000.00 |
| Buffalo | wood shop (power drills) electrical room & FAC hallway | electrical | Electrical wiring exposed | \$500.00 | \$3000.00 |
| Buffalo | dish room | first aid | Emergency eyewash not flushed weekly | \$500.00 | \$1500.00 |
| Buffalo | wood shop | firs protection | 20# propane tank must be stored outside of building | | |
| Buffalo | wood shop | ladders/hammers | Hammer cracked handle | | |
| Buffalo | metal shop | machine guarding | Needs guarding - bearing press | \$500.00 | \$2500.00 |
| Buffalo | metal shop | machine guarding | Strain relief on drop cords needed | | |
| Buffalo | metal shop | machine guarding | Metal lathe needs a shield | | |
| Buffalo | grounds shop | personal protective equipment | PPE required for chain saw | | |
| | • | • | Total | \$4000.00 | \$11000.00 |

Inspected by Mike Weigel Date 10/11/2010