

BRS Facilities Winter Preparedness 2025



November 6th
2025
Facilities
Committee


COMPLETED TASKS

- Started and checked oil in all (4) snow blowers.
- Ice melt is in stock and onsite.
- Completed AERCO Boiler Preventative Maintenance
- Tested functionality of outdoor air dampers on all RTUS, AHUs, and ERVS.
- Completed a whole school walk to check for clear drainage for snow melt
- Checked all vestibule heaters and stand alone heating units located in; loading dock, electrical room, mezzanine, and south gym storage closet.

CONTINUING PREPAREDNESS TASKS

- Frequent monitoring of HVAC controls & alarms during below freezing conditions.
- Foster an open line of communication with the town, landscape contractor, and custodial team for snow removal events.

Beecher Road School Snow Removal Map



CLEAN
HEALTHY
SAFE
SCHOOLS

Prepared by:

Vito Esparo
Facilities Director

Woodbridge School
District
40 Beecher Rd,
Woodbridge, CT
06525
(203) 389-2195