

Work Order ID: 17511

Completion Date:

Description	Tube slide is damaged on lowest part of slide. Please inspect and repair.		
Location	Stowe Elementary School	Building	
Area		Priority	Emergency
Area Number		Craft	Health/Safety
Custom Category		Type	
Status	Work In Progress	Estimated Hour	0.00
Assigned To	Barsness, Jason	Requester	David Spooner 218-336-8700 X 3232
Estimated Start	5/11/2016	Request Date	5/11/2016
Est. Completion Date		Req. Completion Date	
Budget Code		Purpose Code	
Project Code		Project Description	
Equip Item No.		Equip Desc	
Notes			

Purchases						To Date:	\$0.00
Date	Inv/Ref	Description	Supplier	Pool	Qty	Cost Each	

Labor			To Date:	h
Date	Name	Hours		

 Technician Name
 www.schooldude.com MaintenanceDirect

 Date

 Confirmation

 Date
 Printed by David Spooner