

## FACILITIES/CONSTRUCTION REPORT

### SEPTEMBER 2025

#### BMS Renovation/Addition:

9-11 Calm, hot@80 degrees. Mule Hide rep (Juan) inspecting roof, took samples of welded seams, patched holes. Also showed John Bullcalf holes around the west/east edges that he wanted patched, 2 workers.

9-12 Calm, warm@76 degrees. John Bullcalf patching holes on roof, 2 workers.