

# Maintenance & Operations Report 2021

## Central Support Center

- Fabricated small wall section and installed a new door in Accelerated Side of the building
- Painted 1 Office

## High School

- Installed new inserts in floor at Warren Gym for volleyball net poles
- Contractor refinished the floors in both gyms
- Installed (2) 86 inch TVs in the Band Hall
- Removed Dishwasher in Room 401, modified cabinet, and installed commercial type hand wash station
- Modified plumbing in Greenhouse and installed a new PLC Control System to control Humidity and Temperature
- 600 Building Foundation/Slab repair (Contractor)
- Installed new cabinets in the Teacher's Workroom/Breakroom in the 600 Building
- Rebuilt pig barn and increased size by 50% at the Ag Farm
- Performed Bat Remediation (Contractor)
- Installed new Package HVAC unit in Room 108
- New LED lighting was installed in Warren Gym (Donated)

## Middle School

- Painted Choir Hall, Band Hall, Band Instrument Storage Area, Room 101 & 803
- Installed new Commercial Dishwasher in the Kitchen

## East Elementary

- Removed the old Blue Playground Equipment (Safety Issues)
- Installed New Climbing Wall in the Gym
- Repainted and Installed New Carpet in the Music Room

## Coggin Elementary

- Repaired Fire Sprinkler System (Freeze Damage)
- Repaired water damaged walls and suspended ceiling in the Science Room and Lab
- Repaired Stucco and painted 3 upstairs classrooms
- Installed new Partitions in Boys Restroom
- Installed new carpet in 1 Classroom

## Northwest Elementary

- Repaired Wallpaper and painted Room 208
- Installed 1 new Package HVAC unit.

### **Woodland Heights Elementary**

- Installed a wall to divide a large classroom into 2 smaller classrooms
- Painted and installed 8 sets of cubbies in 2 Pre-K classrooms
- Installed new wooden wall panels in the Refocus Room

### **Northwest Headstart**

- Replaced all of carpet in the Facility due to water damage from the Winter Freeze
- Replaced the roof on the Main Building

### **Infant & Toddlers**

- Worked on interior lighting
- Repaired plumbing and water damaged walls from Freeze Damage

### **Gordon Wood Stadium**

- Painted floors in the Men's Restroom and Concession Stand on the Home Side
- The Bronze Plaques on the Memorial Wall were refinished

**Installed 23 Water Bottle Fill Stations throughout the District**